

Sistema de Enfriamiento del Motor

Termostatos



| Fabricante Modelo | Años | Despl. | Cil. | Transmisión | A/C | N° de Parte |
|----------------------|--------------|------------|-------|-------------|-------|--------------|
| Audi | | | | | | |
| A4 | 1997 -> 2005 | 1,8L | 4cil. | | | 1.180.87.302 |
| BMW | | | | | | |
| M5 | 2000 -> 2003 | 5.0L, 5L | 8cil. | Manual | SI | 2.402.79 |
| Serie 3 | 1996 -> 1999 | 1.9L, 1,9L | 4cil. | Aut/Man | SI | 2.416.95 |
| Serie 5 | 1985 -> 1993 | 2.5L, 2,5L | 4cil. | Aut/Man | SI/NO | 2.119.80 |
| | 1985 -> 1993 | 3.5L | 6cil. | Aut/Man | SI/NO | 2.119.80 |
| Z3 | 1996 -> 1999 | 1.9L, 1,9L | 4cil. | Aut/Man | SI | 2.416.95 |
| 325 | 1992 -> 2005 | 2,5L | 6cil. | | | 2.561.01 |
| 525 | 1992 -> 2003 | 2,5L | 6cil. | | | 2.124.88.312 |
| 528 | 1997 -> 2000 | 2,8L | 6cil. | | | 2.124.88.312 |
| 530 | 1992 -> 2005 | 3L | 6cil. | | | 2.561.01 |
| Series 5 | 1999 -> 2005 | 4,4L | 8cil. | | | 2.547.01 |
| Series 7 | 1999 -> 2003 | 4,4L | 8cil. | | | 2.547.01 |
| X3 | 2001 -> 2006 | 2,5L | 6cil. | | | 2.561.01 |
| X5 | 2001 -> 2006 | 4,4L | 8cil. | | | 2.547.01 |
| Z3 | 2001 -> 2002 | 3L | 6cil. | | | 2.561.01 |
| Z4 | 2003 -> 2005 | 2,5L | 6cil. | | | 2.561.01 |
| | 2003 -> 2005 | 3.0L | 6cil. | | | 2.561.01 |
| Chrysler | | | | | | |
| Le Baron | 1983 -> 1993 | 2,5L | 4cil. | | | 1.092.88.349 |
| Neon | 1988 -> 1999 | 2L | 4cil. | | | 1.092.88.349 |
| Shadow | 1988 -> 1999 | 2,2L | 4cil. | | | 1.092.88.349 |
| | 1988 -> 1999 | 2.5L | 4cil. | | | 1.092.88.349 |
| Spirit | 1989 -> 1995 | 2,2L | 4cil. | | | 1.092.88.349 |
| | 1989 -> 1995 | 2.5L | 4cil. | | | 1.092.88.349 |
| Voyager | 1992 -> 2000 | 3L | 6cil. | | | 1.092.88.349 |
| Dodge | | | | | | |
| Durando | 1998 -> 1999 | 3,9L | 6cil. | | | 1.070.92.309 |
| Ram Charger | 1989 -> 1993 | 5,9L | 8cil. | | | 1.070.92.309 |



Sistema de Enfriamiento del Motor

Termostatos

| Fabricante Modelo | Años | Despl. | Cil. | Transmisión | A/C | N° de Parte |
|-----------------------|--------------|--------|-------|-------------|-----|--------------|
| Ford | | | | | | |
| Fiesta | 1998 -> 2001 | 1,3L | 4cil. | | | 1.071.92.305 |
| Focus | 2000 -> 2005 | 2L | 4cil. | | | 1.172.88.350 |
| Freightliner | | | | | | |
| FLD11264T | 1997 -> 1998 | | | | | 2.409.82 |
| FLD 120 | 1994 -> 2004 | | | | | 2.409.82 |
| General Motors | | | | | | |
| Astra | 2001 -> 2003 | 1,8L | 4cil. | | | 1.194.92 |
| | 2002 -> 2003 | 2.2L | 4cil. | | | 1.070.83.309 |
| | 2004 -> 2006 | 2.4L | 4cil. | | | 1.408.92 |
| Astro | 1986 -> 2005 | 4,3L | 6cil. | | | 1.436.92 |
| Blazer | 1996 -> 2000 | 4,3L | 6cil. | | | A.008.88 |
| Chevy | 1996 -> 2003 | 1,6L | 4cil. | | | 1.060.92.300 |
| Express 1500,2500 | 1996 -> 2006 | 4,3L | 6cil. | | | 1.436.92 |
| S-10 | 1988 -> 2004 | 4,3L | 6cil. | | | 1.436.92 |
| | 1996 -> 2000 | 4.3L | 6cil. | | | A.008.88 |
| Trail Blazer | 2002 -> 2007 | 4,2L | 6cil. | | | 2.448.88 |
| Zafira | 2002 -> 2006 | 1,8L | 4cil. | | | 1.194.92 |
| | 2002 -> 2007 | 2.2L | 4cil. | | | 1.070.83.309 |
| Honda | | | | | | |
| Accord | 1995 -> 2000 | 2,2L | 4cil. | | | 6.336.83 |
| | 1998 -> 2007 | 3.0L | 6cil. | | | 6.839.76.399 |
| Prelude | 1992 -> 2001 | 2,2L | 4cil. | | | 6.336.83 |
| | 1992 -> 1996 | 2.3L | 4cil. | | | 6.336.83 |
| S-2000 | 2000 -> 2003 | 2L | 4cil. | | | 6.839.76.399 |
| | 2004 -> 2006 | 2.2L | 4cil. | | | 6.839.76.399 |
| Jeep | | | | | | |
| Cherokee | 1987 -> 2001 | 4L | 6cil. | | | 1.070.92.309 |

Consulte dibujo técnico de termostatos a partir de la página 34.

Pueden existir variantes por modificación de Equipo Original sin previo aviso

Sistema de Enfriamiento del Motor

Termostatos



| Fabricante Modelo | Años | Despl. | Cil. | Transmisión | A/C | N° de Parte |
|----------------------|--------------|--------|-------|-------------|-----|--|
| Jeep | | | | | | |
| Grand Cherokee | 1993 -> 2004 | 4L | 6cil. | | | 1.070.83.309 1.070.92.309 |
| | 1999 -> 2006 | 4.7L | 8cil. | | | 1.070.92.309 |
| | 1993 -> 1998 | 5.2L | 8cil. | | | 1.070.92.309 |
| | 1998 | 5.9L | 8cil. | | | 1.070.92.309 |
| Wagoneer | 1984 -> 1986 | 4,2L | 6cil. | | | 1.070.92.309 |
| | 1993 | 5.2L | 8cil. | | | 1.070.92.309 |
| | 1984 -> 1991 | 5.9L | 8cil. | | | 1.070.92.309 |
| Wrangler | 1991 -> 2006 | 4L | 6cil. | | | 1.070.92.309 |
| | 1987 -> 1990 | 4.2L | 6cil. | | | 1.070.92.309 |
| Mercedes-Benz | | | | | | |
| 904,906,457,460 | 2002 -> 2008 | 4,6L | | | | 2.085.71.300 2.085.79.300 2.085.83.300 |
| C240 | 2001 -> 2005 | 2,6L | 6cil. | | | 6.617.87.399 |
| C280 | 1998 -> 2000 | 2,8L | 6cil. | | | 6.617.87.399 |
| C320 | 2002 -> 2005 | 3,2L | 6cil. | | | 6.617.87.399 |
| C430 AMG | 1998 -> 2000 | 4,3L | 8cil. | | | 6.617.87.399 |
| C55 | 2005 -> 2006 | 5,5L | 8cil. | | | 6.617.87.399 |
| CL500 | 1998 -> 2006 | 5L | 8cil. | | | 6.617.87.399 |
| CLK430 | 1999 -> 2003 | 4,3L | 8cil. | | | 6.617.87.399 |
| CLK500 | 2003 -> 2005 | 5L | 8cil. | | | 6.617.87.399 |
| CLK550 | 2007 -> | 5,5L | 8cil. | | | 6.617.87.399 |
| CLK 320 | 1998 -> 2005 | 3,2L | 6cil. | | | 6.617.87.399 |
| E320 | 1998 -> 2005 | 3,2L | 6cil. | | | 6.617.87.399 |
| E430 | 1998 -> 2002 | 4,3L | 8cil. | | | 6.617.87.399 |
| E500 | 2003 -> 2005 | 5L | 8cil. | | | 6.617.87.399 |
| Sprinter | 2003 -> 2007 | 2,7L | 5cil. | | | 2.426.87.355 |
| Nissan | | | | | | |
| Sentra | 1996 -> 2000 | 1,6L | 4cil. | | | 6.822.77 |
| Tsuru | 1991 -> 2007 | 1,6L | 4cil. | | | 6.822.77 |



Sistema de Enfriamiento del Motor

Termostatos

| Fabricante Modelo | Años | Despl. | Cil. | Transmisión | A/C | N° de Parte |
|----------------------|--------------|--------|-------|-------------|-------|--------------|
| Peugeot | | | | | | |
| 206 | 2000 -> 2007 | 1,6L | 4cil. | | | 6.703.89 |
| 306 | 2000 -> 2003 | 1,8L | 4cil. | | | H.040.83 |
| 307 | 2003 -> 2006 | 2L | 4cil. | | | H.045.89 |
| Partner | 2003 -> 2007 | 1,6L | 4cil. | | | H.047.89 |
| Seat | | | | | | |
| Cordoba | 2000 -> 2007 | 1,6L | 4cil. | | | 6.500.87.320 |
| Ibiza | 2000 -> 2007 | 1,6L | 4cil. | | | 6.500.87.320 |
| VW | | | | | | |
| Golf | 1984 -> 1992 | 1,8L | 4cil. | Manual | SI/NO | 1.173.92.300 |
| | 1984 -> 1992 | 2.0L | 4cil. | Manual | SI/NO | 1.173.92.300 |
| Jetta | 1984 -> 1992 | 1,8L | 4cil. | Manual | SI/NO | 1.173.92.300 |
| | 1984 -> 1992 | 2.0L | 4cil. | Manual | SI/NO | 1.173.92.300 |
| Derby | 1995 -> 2007 | 1,8L | 4cil. | | | 1.186.87.302 |
| Eurovan TDI | 2006 -> | 1,9L | 4cil. | | | 1.186.87.302 |
| Golf A3 | 1993 -> 2000 | 2L | 4cil. | | | 1.180.87.302 |
| Golf A4 | 2000 -> 2005 | 1,8L | 4cil. | | | 1.180.87.302 |
| | 1993 -> 2007 | 2.0L | 4cil. | | | 1.180.87.302 |
| Jetta A3 | 1994 -> 2000 | 1,8L | 4cil. | | | 1.180.87.302 |
| | 1993 -> 1999 | 2.0L | 4cil. | | | 1.180.87.302 |
| Jetta A4 | 2000 -> 2005 | 1,8L | 4cil. | | | 1.180.87.302 |
| | 1999 -> 2007 | 2.0L | 4cil. | | | 1.180.87.302 |
| New Beetle | 2001 -> 2005 | 1,8L | 4cil. | | | 1.180.87.302 |
| | 1999 -> 2007 | 2.0L | 4cil. | | | 1.180.87.302 |
| Passat | 2001 -> 2005 | 1,8L | 4cil. | | | 1.180.87.302 |
| | 1990 -> 1993 | 2.0L | 4cil. | | | 1.180.87.302 |
| Pointer | 1998 -> 2007 | 1,8L | 4cil. | | | 1.186.87.302 |

Consulte dibujo técnico de termostatos a partir de la página 34.

Pueden existir variantes por modificación de Equipo Original sin previo aviso

Sistema de Enfriamiento del Motor

Termostatos



| | | |
|---|---|---|
| <p>2.124.88.312 BMW</p> <p>2.124</p> | <p>2.547.01 BMW</p> <p>2.547</p> | <p>2.561.01 BMW</p> <p>2.561</p> |
| <p>1.092.88.349 Chrysler</p> <p>1.092</p> | <p>1.070.92.309 Dodge</p> | <p>1.071.92.305 Ford</p> |
| <p>1.172.88.350 Ford</p> <p>1.172</p> | <p>1.060.92.300 General Motors</p> <p>1.060</p> | <p>1.070.83.309 General Motors</p> |
| <p>1.173.92.300 VW</p> <p>1.173</p> | <p>1.194.92 General Motors</p> <p>1.194</p> | <p>1.408.92 General Motors</p> <p>1.408</p> |
| <p>1.436.92 General Motors</p> <p>1.436</p> | <p>2.448.88 General Motors</p> <p>2.448</p> | <p>A.008.88 General Motors</p> |



Sistema de Enfriamiento del Motor

Termostatos





| | | |
|--|-----------------------------------|--|
| <p>6.336.83 Honda</p> | <p>6.839.76.399 Honda</p> | <p>2.085.71.300 Mercedes-Benz</p> |
| <p>2.085.79.300 Mercedes-Benz</p> | <p>2.085.83.300 Mercedes-Benz</p> | <p>2.119.80 BMW</p> <p>2.119</p> |
| <p>2.402.79 BMW</p> <p>2.402</p> | <p>2.416.95 BMW</p> <p>2.416</p> | <p>2.426.87.355 Mercedes-Benz</p> <p>2.426</p> |
| <p>6.617.87.399 Mercedes-Benz</p> <p>6.617</p> | <p>6.822.77 Nissan</p> | <p>6.703.89 Peugeot</p> <p>6.703</p> |
| <p>H.040.83 Peugeot</p> <p>H.040</p> | <p>H.045.89 Peugeot</p> | <p>H.047.89 Peugeot</p> <p>H.047</p> |

Pueden existir variantes por modificación de Equipo Original sin previo aviso

Sistema de Enfriamiento del Motor

Termostatos



| | | |
|--|--|--|
| <p>2.409.82 Freightliner</p>  <p>2.409</p> | <p>6.500.87.320 Seat</p>  <p>6.500</p> | <p>1.180.87.302 Audi</p>  <p>1.180</p> |
| <p>1.186.87.302 VW</p>  | | |